


NOTES:

1. REMOVE JUMPER JA TO PREVENT HANDSWITCH INITIATED MOTION
2. J1 AND J2 ARE REQUIRED AS SHOWN
3. 120VAC ALARM AVAILABLE BETWEEN TERMINALS B AND E.
4. CONNECTING LINE 3 OF 3 PHASE POWER TO TERMINAL 3 IS PERMISSIBLE, BUT NOT REQUIRED.

UNUSED



17-7000-220 A

SIZE:  
**A**

## HAROLD BECK & SONS INC

NEWTOWN INDUSTRIAL COMMONS NEWTOWN, PENNSYLVANIA 18940 USA

TITLE:

**WIRING DIAGRAM GROUP 11-1X9/2X9/3X9/409/419/469**  
**380/415/480/575 VOLT 0 AUX SWITCHES INT CPS**  
**W/ HART/LOCAL DCM**

THIS DOCUMENT IS A COPY AND IS NOT THE SOURCE DOCUMENT. INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. THE INFORMATION CONTAINED HEREIN IS COPYRIGHTED BY HAROLD BECK AND SONS, INC. CHANGES TO THE DOCUMENT ARE PROHIBITED. CONTACT A BECK SALES ENGINEER IF A CERTIFIED DRAWING IS REQUIRED.

DRAWN:  
GMD 12/18/08

SCALE:  
NONE

DRAWING NO:

REV:

CHECKED:  
DMS/BP 12/18/08

**17-7000-220**

**A**

APPROVED:  
JHM 12/18/08

SHEET NO. 1 OF 1